

Inspection Photos

API: 071-07405

Operator: OGRIS OPERATING LLC

Inspection Date: 5/17/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07405 | Date: 5/17/2021

Inspection Photos



Photo 1. Facing southeast along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07405 | Date: 5/17/2021

Inspection Photos



Photo 2. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07405 | Date: 5/17/2021

Inspection Photos



Photo 3. The interim reclamation area is stabilized with perennial vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07405 | Date: 5/17/2021