

Inspection Photos
Location Name: Federal 5-27X
Location ID: 324684



Photo 1. Overview of location taken facing east.



Photo 2. No bradenhead access apparent. Stained soil at wellhead.

