

Inspection Photos
Location Name: Federal 12-27
Location ID: 324687




Photo 1. No bradenhead access apparent.



Photo 2. Stained soil under pump jack.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources