

# Inspection Photos

API: 025-06020

Operator: CRAZY 8 ENERGY LLC

Inspection Date: 5/12/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 025-06020 | Date: 5/12/2021

## Inspection Photos



**Photo 1.** Center of the location facing north. There are undesirable weeds growing throughout the location which is shown in photo 5.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 025-06020 | Date: 5/12/2021

## Inspection Photos



**Photo 2.** Center of the location facing west. There are undesirable weeds growing throughout the location which is shown in photo 5.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 025-06020 | Date: 5/12/2021

## Inspection Photos



**Photo 3.** Center of the location facing south. There are undesirable weeds growing throughout the location which is shown in photo 5.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 025-06020 | Date: 5/12/2021

## Inspection Photos



**Photo 4.** Center of the location facing east. There are undesirable weeds growing throughout the location which is shown in photo 5.



## Inspection Photos



**Photo 5.** View of ground cover shows mostly undesirable weeds (Kochia). There is a few desirable species shown at red arrows. The rest of the vegetation growth shown is Kochia sp.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 025-06020 | Date: 5/12/2021