

Inspection Photos

5/14/2021

Operator: LARAMIE ENERGY LLC #10433

Location ID: 324315

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 324315



Photo 1: Photo taken from the north end of the Location, facing east. Photos 1-5 provide an overview of the Location from east, southeast, south, southwest to west. Photos also show reclamation of areas not needed for production has not been performed in accordance with 1003 Rules.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 324315



Photo 2: See comments under photo 1.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 324315



Photo 3: See comments under photo 1.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 324315



Photo 4: See comments under photo 1.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 324315



Photo 5 See comments under photo 1.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 324315



Photo 6: Photo taken from the southeast of the Location, facing northwest. See comments under photo 1. Control measures to protect/stabilize the fill slopes of the Location remain missing or insufficient.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 324315



Photo 7: Photo taken from the cut slopes of the Location, facing north. Photo shows control measures to protect/stabilize the cut and fill slopes of the Location remain missing or insufficient.

