

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Nolte /14-44

Location ID: 334568



Photo #3837 from entrance to location.



Photo #3838 from entrance to location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Nolte /14-44

Location ID: 334568



Photo #3839 Location lacks stabilization



Photo #3840 Location lacks stabilization

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Nolte /14-44

Location ID: 334568



Photo #3842 No form of tracking BMP located at the entrance to location.



Photo #3843 No sign located at the tank battery.

