

## Inspection Photos

**Location Name: TEP ROCKY MOUNTAIN LLC Bosely /SG 14-23**

**Location ID: 334689**



**Photo #3851 from entrance to location.**



**Photo #3852 from entrance to location.**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Bosely /SG 14-23

Location ID: 334689



**Photo #3854 Location lacks stabilization.**



**Photo #3078 from inspection #699802719 conducted on 3/8/21.**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Bosely /SG 14-23

Location ID: 334689



**Photo #3855 No form of tracking BMP at entrance to location.**



**Photo #3079 from inspection #699802719 conducted on 3/8/21**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Bosely /SG 14-23

Location ID: 334689



**Photo #3853 No battery sign located at the tank battery.**

