

Inspection Photos
Location Name: Weld-Weitzel 11-33
Location ID: 317747



Photo 1 – Tank Battery, NFPA Label Faded



Photo 2 – Tank Battery, NFPA Label Faded

Inspection Photos
Location Name: Weld-Weitzel 11-33
Location ID: 317747



Colorado Oil and Gas Conservation Commission
40.52945, -104.10163, 4897.1ft, 148°
05/18/2021 12:30:09



Colorado Oil and Gas Conservation Commission
40.52945, -104.10171, 4899.0ft, 228°
05/18/2021 12:30:17

Photo 3 – Tank Battery, Weeds

Photo 4 – Heater Treater

Inspection Photos
Location Name: Weld-Weitzel 11-33
Location ID: 317747



Photo 5 – Heater Treater



Photo 6 – Stained Soil at Heater Treater

Inspection Photos
Location Name: Weld-Weitzel 11-33
Location ID: 317747



Photo 7 – Stained Soil at Heater Treater

Photo 8 – Tank Battery Sign

Inspection Photos
Location Name: Weld-Weitzel 11-33
Location ID: 317747



Photo 9 – Produced Water Tank, Weeds



Photo 10 – Produced Water Tank, Weeds

Inspection Photos
Location Name: Weld-Weitzel 11-33
Location ID: 317747



Photo 11 – Wellhead



Photo 12 – Wellhead Sign

Inspection Photos
Location Name: Weld-Weitzel 11-33
Location ID: 317747



Photo 13 – Stained Soil at Gas Engine



Photo 14 – Stained Soil at Gas Engine

