



39.79124, -108.61772, 6388.7ft, 230°
05/17/2021 10:07:34 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Separator & pump jack.

Continental 1-16

API: 05-103-08037

Inspection: 701500804



39.79118, -108.61778, 6392.8ft, 221°
05/17/2021 10:06:41 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well.

Continental 1-16

API: 05-103-08037

Inspection: 701500804



39.79118, -108.6178, 6391.0ft, 17°
05/17/2021 10:06:27 AM



39.79141, -108.61761, 6388.0ft, 134°
05/17/2021 10:08:53 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Tank.

Continental 1-16

API: 05-103-08037

Inspection: 701500804



39.79118, -108.61778, 6379.4ft, 307°
05/17/2021 10:10:14 AM



39.79118, -108.61776, 6388.2ft, 281°
05/17/2021 10:09:52 AM



39.79118, -108.61777, 6381.5ft, 299°
05/17/2021 10:10:31 AM



39.79114, -108.61756, 6371.4ft, 279°
05/17/2021 10:11:27 AM



39.789, -108.61782, 6347.8ft, 200°
05/17/2021 10:14:58 AM