

Inspection Photos
Location Name: Perry 1
Location ID: 318572



Pic 1



Pic 2

Inspection Photos
Location Name: Perry 1
Location ID: 318572



Pic 3



Pic 4 gas line from gas meter run LOTO

Inspection Photos

Location Name: Perry 1
Location ID: 318572



Pic 5



Pic 6 gas meter run needs calibration.