

Inspection Photos
Location Name: Sirios Brothers 2A
Location ID: 317965




Photo 1 WH sign, inaccurate well name

Photo 2 WH

Inspection Photos
Location Name: Sirios Brothers 2A
Location ID: 317965



Photo 3 Trash near WH

Photo 4 Dead weeds around WH

Inspection Photos
Location Name: Sirios Brothers 2A
Location ID: 317965



Photo 5 Dead weeds near WH and across access.

Photo 6 TB sign

Inspection Photos
Location Name: Sirios Brothers 2A
Location ID: 317965



Photo 7 TB.

Photo 8 Horizontal Heated Separator

Inspection Photos
Location Name: Sirios Brothers 2A
Location ID: 317965



Photo 9 dead weeds around location



Photo 10 Gas Meter Run card in box indicates that calibration is not current.

Inspection Photos
Location Name: Sirius Brothers 2A
Location ID: 317965



Photo 11 Trash at the backside of the Crude tank

Photo 12 Dead weeds on, in & around TB berm

Inspection Photos
Location Name: Sirius Brothers 2A
Location ID: 317965



Photo 13 Dead weeds on, in & around TB berm

Photo 14 Dead weeds on, in & around TB berm