

Inspection Photos
Location Name: Cooper 1
Location ID: 318519



Photo 1 Weeds growing over access road

Photo 2 WH sign

Inspection Photos
Location Name: Cooper 1
Location ID: 318519



Photo 3 WH



Photo 4 Gas meter Run



Inspection Photos
Location Name: Cooper 1
Location ID: 318519




Photo 5 Card in meter house indicates that calibration is not current.

Photo 6 Weeds throughout location

Inspection Photos
Location Name: Cooper 1
Location ID: 318519



Photo 7 Weeds throughout location

Photo 8 Vertical Separator

Inspection Photos
Location Name: Cooper 1
Location ID: 318519



Photo 9 TB sign



Photo 10 TB