

Inspection Photos

API#103-07039

Operator: Caerus

Insp#:692403370

Insp Date: 5/6/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Overview of Location from entry & drive through road leading to Northeast.

May 6, 2021



Photo#2:
View over pad & stock pond to Southwest.

May 6, 2021



Photo#3:
Pit utilized as stock Pond.



Photo#4:
Down Marker.

May 6, 2021