

Inspection Photos

API#081-05008

Operator: Caerus

Insp#:692403372

Insp Date: 5/6/21





Photo#1:

Overview of Location from South end to North entry and access road.

May 6, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus PA Lewin Thornburg API#081-05008



Photo#2:

View over Location from entry to Southwest. Insert, showing ground conditions/vegetation on pad surface.

May 6, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus PA Lewin Thornburg API#081-05008



Photo#3:
Access road leading out of Location to North.



Photo#4:
What appears to be Topsoil pile, berm at
South end of site.

May 6, 2021