

Inspection Photos

API#081-06172

Operator: Caerus

Insp#:692403373

Insp Date: 5/6/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry to North.

May 6, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus PA Thornburg API#081-06172



Photo#2:
View over pad to South.

May 6, 2021



Photo#3:
Access road at entry into Location.

May 6, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#4:
View along cut slope to North.

Caerus PA Thornburg API#081-06172



Photo#5:
Edge of Pad and fill slope area.

May 6, 2021



Photo#6:
Close up of Pad vegetation.