

# *Inspection Photos*

*API#081-05006*

*Operator: Caerus*

*Insp#:692403374*

*Insp Date: 5/6/21*






Photo#1:  
Long overview of Location from ranch road

May 6, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#2:  
Long overview of Location from ranch road

Caerus PA Henderson-Thornburg API#081-05006



Photo#3:  
Road leading into Location.

Photo#4:  
Road leading out of Location.

May 6, 2021



Photo#5:  
View over Pad to North. Insert, close up of pad vegetation.

May 6, 2021



Photo#6:  
Old Pit area @ Southwest corner.



Photo#7:  
PA Marker.



Photo#8:  
Old pit area @Southeast corner

May 6, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus PA Henderson-Thornburg API#081-05006