



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

**Woosley 2**

**API: 05-103-40370**  
**Inspection: 701500818**





**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Well.**

**Woosley 2**

**API: 05-103-40370**

**Inspection: 701500818**





40.07366, -108.78164, 5341.5ft, 327°  
05/18/2021 04:00:53 PM









**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 5. Tanks.**

**Woosley 2**

**API: 05-103-40370**

**Inspection: 701500818**





**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 6. Top of lower tank.**

**Woosley 2**

**API: 05-103-40370**

**Inspection: 701500818**





40.07383, -108.78106, 5320.0ft, 136°  
05/18/2021 04:25:41 PM













40.07372, -108.78177, 5334.3ft, 329°  
05/18/2021 04:02:08 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 10. Concrete trash.**

**Woosley 2**

**API: 05-103-40370**

**Inspection: 701500818**