

Inspection Photos

Location Name: LARAMIE ENERGY LLC NVega /3B Pad

Location ID: 334467



Photo #3875 from entrance to location.



Photo #3876 from entrance to location.

Inspection Photos

Location Name: LARAMIE ENERGY LLC NVega /3B Pad

Location ID: 334467



Photo #3881 No tank battery sign located at the tank battery.



Photo #3877 Location lacks stabilization.

Inspection Photos

Location Name: LARAMIE ENERGY LLC NVega /3B Pad

Location ID: 334467



Photo #3879 Location lacks stabilization.



Photo #3880 No form of tracking BMP located at the entrance to location.