

**Inspection Photos**  
**Location Name: Arthur Scheetz #1**  
**Location ID: 317520**



**Photo 1 – Pumping Unit**



**Photo 2 – Wellhead**

**Inspection Photos**  
**Location Name: Arthur Scheetz #1**  
**Location ID: 317520**



**Photo 3 – Gear Box leaking to Soil**



**Photo 4 – Gear Box leaking to Soil**





**Inspection Photos**  
**Location Name: Arthur Scheetz #1**  
**Location ID: 317520**



**Photo 5 – Tank Battery Sign**



**Photo 6 – Tank Battery**



**Inspection Photos**  
**Location Name: Arthur Scheetz #1**  
**Location ID: 317520**



**Photo 7 – Pit**



**Photo 8 – Heater Treater**