

Inspection Photos
Operator: Simcoe
API: 067-09617
Date: 5/19/2021



Photo 1. View of project area from well pad entrance facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing with western wheatgrass, crested wheatgrass, and rubber rabbitbrush.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of the reference area (beyond fenceline) comprised of sagebrush shrubland with big sagebrush, western wheatgrass, crested wheatgrass, Indian paintbrush, and scattered juniper trees observed.



Photos 5/6. View of closed gates at after leaving location.