

Wallach 1-8H Photographs
Inspection Doc # 696303142
Loc ID 431888
API No. 123-36841



Stained soil and unused pipe removed.