

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Savage /GV 80-4

Location ID: 334813



Photo #3884 from entrance to location.



Photo #3885 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Savage /GV 80-4

Location ID: 334813



Photo #3886 Location lacks stabilization.



Photo #3242 from inspection #699802807 conducted on 3/23/21.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Savage /GV 80-4

Location ID: 334813



Photo #3887 Location lacks stabilization.



Photo #3244 from inspection #699802807 conducted on 3/23/21.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Savage /GV 80-4

Location ID: 334813



Photo #3888 No form of tacking BMP located at the entrance to location.



Photo #3243 from inspection #699802807 conducted on 3/23/21.