

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA-67S95W /9NENE

Location ID: 334964



Photo #3899 from entrance to location.



Photo #3900 from entrance to location.



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA-67S95W /9NENE

Location ID: 334964



Photo #3901 Location lacks stabilization



Photo #3902 Location lacks stabilization.



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BATTLEMENT MESA-67S95W /9NENE

Location ID: 334964



Photo #3903 No form of tracking BMP located at the entrance to location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources