

Planck 1-14H Photographs
Inspection Doc # 696303144
Loc ID 424707
API No. 123-34144



Stained soil removed from loading area



Stained soil removed from wellhead



Stained soil removed from engine