

# Inspection Photos

API: 055-06283

Operator: EDWARDS ENERGY CORPORATION

Inspection Date: 5/20/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06283 | Date: 5/20/2021

## Inspection Photos



**Photo 1.** Facing south along the former access road which appears to be mostly pre-existing. There is erosion occurring along areas of the road which need to be stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06283 | Date: 5/20/2021

## Inspection Photos



**Photo 2.** The culvert installed along the access road is not maintained and stormwater is bypassing the culvert. Lat/Long:37.50521,-105.07444.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06283 | Date: 5/20/2021

## Inspection Photos



**Photo 3.** Facing northeast toward the location which was never recontoured and reclaimed per 1004 Rules.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06283 | Date: 5/20/2021

## Inspection Photos



**Photo 4.** There are four guy line anchors that remain which should have been removed within 3 months of abandoning the well.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06283 | Date: 5/20/2021

## Inspection Photos



**Photo 5.** Facing northeast toward the pit which was never backfilled and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06283 | Date: 5/20/2021

## Inspection Photos



**Photo 6.** Facing southwest toward the pit which is approximately 100'x100' in size.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06283 | Date: 5/20/2021

## Inspection Photos



**Photo 7.** Facing southeast along the fill slope of the location which was never recontoured back to the original contours of the terrain.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06283 | Date: 5/20/2021

## Inspection Photos



**Photo 8.** Facing northeast toward the surrounding undisturbed pasture which consists of perennial native vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06283 | Date: 5/20/2021