

Inspection Photos

API: 055-06096

Operator: EDWARDS ENERGY CORPORATION

Inspection Date: 5/20/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06096 | Date: 5/20/2021

Inspection Photos



Photo 1. Drone aerial photo facing north toward the access road leading to the location shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06096 | Date: 5/20/2021

Inspection Photos



Photo 2. Drone aerial photo of the location. The access road continues past the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06096 | Date: 5/20/2021

Inspection Photos



Photo 3. There is erosion evident show at red arrows. The area where tank was location is bare of vegetation growth shown at yellow arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06096 | Date: 5/20/2021