

Inspection Photos
Location Name: Opal #14-34
Location ID: 318936



Photo 1 Production Tank not markings or placards. Tank not painted



Photo 2 production equipment not painted.

Inspection Photos
Location Name: Opal #14-34
Location ID: 318936



Photo 3 crude oil tank no markings or placards. Tank not painted.

Photo 4 unmarked not LOTO risers.