

# Final Reclamation Inspection

May 18, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 330051

Inspection Document #: 697502915

Weld County, CO

SESE Section 33 T3N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HSR-PAUL SCHMIDT #16-33  
Location ID: 330051



**Photo 1.** Photo taken from the northern well location access road, facing South. Photo illustrates Operator has performed final reclamation activities with the evidence of desirable establishment throughout the access road and well location.

Inspection Photos  
Location Name: HSR-PAUL SCHMIDT #16-33  
Location ID: 330051



**Photo 2.** Photo taken from a portion of the well location access road, facing South. See comments under Photo 1.

Inspection Photos  
Location Name: HSR-PAUL SCHMIDT #16-33  
Location ID: 330051



**Photo 3.** Photo taken from the central well location access road, facing South. Photo illustrates the vegetated access road and well location. Most of the well location is now associated with a new housing development.

## Inspection Photos

Location Name: HSR-PAUL SCHMIDT #16-33

Location ID: 330051



**Photo 4.** Aerial photo from 2011 illustrates the associated offsite tank battery. The associated offsite tank battery has been removed and now a new tank battery facility has been constructed- see Photo 3.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 697502915

Inspection Photos  
Location Name: HSR-PAUL SCHMIDT #16-33  
Location ID: 330051



**Photo 5.** Aerial photo from 2019 illustrates the new tank battery facility.