

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/20/2021

Submitted Date:

05/24/2021

Document Number:

701003002

**FIELD INSPECTION FORM**

Loc ID 321910 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10634  
 Name of Operator: P O & G OPERATING LLC  
 Address: 5847 SAN FELIPE SUITE 3200  
 City: HOUSTON State: TX Zip: 77057

**Findings:**

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Woll, Chris	512-431-9435	christopher_woll@pogresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208486	WELL	SI	11/01/2020	OW	017-07421	SCHENK 1	SI

**General Comment:**

Routine Inspection

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Partially elevated gravel road through CRP		
Corrective Action:		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Lease sign at tank battery		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tanks and treater		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Sticker on chemical drum		
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:			
Corrective Action:		Date:	_____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Vertical Heater Treater	# 0		
Comment:	Removed from location and replaced with FWKO		
Corrective Action:		Date:	
Type: FWKO	# 1		
Comment:	FWKO on south side of tank battery		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 208486 Type: WELL API Number: 017-07421 Status: SI Insp. Status: SI

**Producing Well**

Comment: [Producing. Central tank battery for \(Schenk 1 & 2\) 500' W @ 38.948150/-102.370590](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT