

Final Reclamation Inspection

May 18, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 149021

Inspection Document #: 697502921

Weld County, CO

SW Section 34 T3N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DRILLING FLUID MANAGEMENT
FACILITY #1
Location ID: 149021



Photo 1. Photo taken from the western DFMF #1, facing North. Photo illustrates Operator is removing and reclaiming the facility berms, outfall BMP and access roads in preparation for site closure.

Inspection Photos

Location Name: DRILLING FLUID MANAGEMENT

FACILITY #1

Location ID: 149021



Photo 2. Photo taken from the western DFMF #1, facing East. See comments under Photo 1.

Inspection Photos

Location Name: DRILLING FLUID MANAGEMENT

FACILITY #1

Location ID: 149021



Photo 3. Photo taken from the western DFMF #1, facing South. See comments under Photo 1.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697502921

Inspection Photos

Location Name: DRILLING FLUID MANAGEMENT FACILITY #1

Location ID: 149021




Photo 4. Figure taken from the most recent Form 4 Sundry attachment illustrating the planned reclamation work.

