

**Inspection Photos**  
**Location Name: Elk Springs Unit 1-17**  
**Location ID: 313039**



**Photo 1. Overview of location taken facing east.**



**Inspection Photos**  
**Location Name: Elk Springs Unit 1-17**  
**Location ID: 313039**



**Photo 2. Stained soil around wellhead.**



**Photo 3. Stained soil at pump jack.**




**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Location Name: Elk Springs Unit 1-17**  
**Location ID: 313039**



**Photo 4. Example of soil staining on location.**



**Photo 5. No bradenhead access apparent.**

