

Inspection Photos
Location Name: Elk Springs Unit 14-8
Location ID: 313035



Photo 1. Overview of location taken facing east.



Photo 3. Stained soil at wellhead.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources