

Inspection Photos
Location Name: Elk Springs Unit 23B-8
Location ID: 313042



Photo 1. Overview of location taken at entrance facing east.



Inspection Photos
Location Name: Elk Springs Unit 23B-8
Location ID: 313042



Photo 2. Stained soil at wellhead.



Photo 3. Stained soil at pumpjack.



Inspection Photos
Location Name: Elk Springs Unit 23B-8
Location ID: 313042



Photo 4. Stained soil on location.



Photo 5. Stained soil on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources