

Inspection Photos  
Location Name: Fuqua 19-02-10-1H  
Location 324766  
May 21, 2021



Location sign. Note incorrect operator information.



Wellhead sign. Note incorrect operator information. And staining in front of and behind well.

# Inspection Photos

Location Name: Fuqua 19-02-10-1H

Location 324766

May 21, 2021



Unmarked chemical storage unit.



Unmarked chemical storage unit.

Inspection Photos  
Location Name: Fuqua 19-02-10-1H  
Location 324766  
May 21, 2021



Unmarked and not cap riser.

Unmarked and not cap riser.

# Inspection Photos

Location Name: Fuqua 19-02-10-1H

Location 324766

May 21, 2021



Tank 001064



Tank 001063.



# Inspection Photos

Location Name: Fuqua 19-02-10-1H

Location 324766

May 21, 2021



**View of tank battery. Operator information is not correct.**



**Trash/debris.**



# Inspection Photos


Location Name: Fuqua 19-02-10-1H

Location 324766

May 21, 2021



Apparent leak near a valve on the separator.



Apparent leak near a valve on the separator.

## Inspection Photos

Location Name: Fuqua 19-02-10-1H

Location 324766

May 21, 2021



Staining of soil, concrete pad, and building from apparent leak.



Staining of soil, concrete pad, and building from apparent leak. Note: weeds.



# Inspection Photos

Location Name: Fuqua 19-02-10-1H

Location 324766

May 21, 2021



**Unlabeled AST.**



**Soil staining within treater building.**

## Inspection Photos

Location Name: Fuqua 19-02-10-1H

Location 324766

May 21, 2021



**Soil staining.**



**Condensate from apparent valve leak,**

# Inspection Photos

Location Name: Fuqua 19-02-10-1H

Location 324766

May 21, 2021



**Build up of tumble weeds.**



**Weeds across the Location.**