

Inspection Photos

5/14/2021

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335915

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335915



Photo 1: Photo taken from the Location entrance. Photo shows signage stating "Location received an approved variance for delayed interim reclamation". Location did not receive a variance to delay interim reclamation.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335915



Photo 2: Photo taken from the south end of the Location, facing west Photos 2-5 provide an overview of the Location from west, northwest, northeast to east. Photos show interim reclamation has not been conducted on the Location.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335915



20210514

Photo 3: See comments under photo 2.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335915



Photo 4: See comments under photo 2. Photo also shows trash debris observed on site.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335915



Photo 5: See comments under photo 2.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335915



Photo 6: Photo taken from the south side of the tank battery; photo shows various unused pipe equipment stored on the site; unused equipment requires removal.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335915



Photo 7: Photo taken from the southeast end of the Location. Photo shows a Operator in process of hauling material from sediment traps in the Crystal Creek area, and placing /storing on the Location. Operator stated in an email that TEP have “historically used sediment trap clean out materials to supplement top soil for any reclaims that may be going on in the local area”.