

# Inspection Photos

5/14/2021

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324411

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location ID: 324411



**Photo 1:** Photo taken from the north end of the Location, facing southeast. Photos 1-3 provide an overview of the Location from southeast, south to southwest. Photos show interim reclamation of the Location has not been conducted in accordance with 1003 rules.



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location ID: 324411



**Photo 2:** See comments under photo 1.





Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location ID: 324411



**Photo 3:** See comments under photo 1. Photo also shows soil materials stored on the western area of the Location.



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location ID: 324411



**Photo 4:** Photo taken from the wells. Permits for undrilled wells on the Location have been deleted. Photo shows conductor settings/cellars require closure and reclamation in accordance with Rule 406.e.





## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324411



**Photo 5:** Photo taken from the western end of the Location, facing north. Photo shows soil materials stored on the Location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources