

Final Reclamation Inspection

May 18, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 336094

Inspection Document #: 697502923

Weld County, CO

SENE Section 33 T3N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: UPV-63N66W /33SENE
Location ID: 336094



Photo 1. Photo taken from the associated offsite tank battery location, facing West. Photo illustrates the tank battery appears reflective of reference areas.

Inspection Photos
Location Name: UPV-63N66W /33SENE
Location ID: 336094



Photo 2. Photo taken from a section of the well location access road, facing South. Photo illustrates the access road is evident, lacking crop growth, which is not reflective of reference areas.



Inspection Photos
Location Name: UPV-63N66W /33SENE
Location ID: 336094



Photo 3. Photo taken from the eastern well location, facing North. See comments under Photo 2.



Inspection Photos
Location Name: UPV-63N66W /33SENE
Location ID: 336094



Photo 4. Photo taken of the western well location, facing West. See comments under Photo 2.