

Final Reclamation Inspection

May 18, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 329911

Inspection Document #: 697502925

Weld County, CO

NENE Section 33 T3N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: UPV-63N66W /33NENE
Location ID: 329911



Photo 1. Photo taken from the associated offsite tank battery location, facing South. Photo illustrates subsidence possibly associated with Remediation Project #4185.

Inspection Photos
Location Name: UPV-63N66W /33NENE
Location ID: 329911



Photo 2. Photo taken of the well location access road and well location, facing South. Photo illustrates the access road and well location are evident, lacking crop growth, which is not reflective of reference areas.