

Final Reclamation Inspection

May 18, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 327358

Inspection Document #: 697502927

Weld County, CO

NWNE Section 33 T3N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SARCHET UPRR-63N66W /33NWNE
Location ID: 327358



Photo 1. Photo taken from the associated offsite tank battery location, facing South. Photo illustrates the tank battery appears reflective of reference areas.

Inspection Photos

Location Name: SARCHET UPRR-63N66W /33NWNE

Location ID: 327358



Photo 2. Photo taken from the associated offsite tank battery location, facing East.
See comments under Photo 1.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697502927

Inspection Photos
Location Name: SARCHET UPRR-63N66W /33NWNE
Location ID: 327358



Photo 3. Photo taken from the associated offsite tank battery location, facing North. Photo illustrates active midstream equipment, which appears to be associated with nearby active locations.

Inspection Photos
Location Name: SARCHET UPRR-63N66W /33NWNE
Location ID: 327358



Photo 4. Photo taken from the western well location access road, facing East. Photo illustrates the access road is evident, lacking crop growth, which is not reflective of reference areas.