

Inspection Photos

API: 071-08897

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 5/24/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08897 | Date: 5/24/2021

Inspection Photos



Photo 1. Facing southwest along the access road. There are areas along the road that have vehicle rutting and erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08897 | Date: 5/24/2021

Inspection Photos



Photo 2. There is a sediment trap along the access road that is filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08897 | Date: 5/24/2021

Inspection Photos



Photo 3. Facing west toward the location.



Inspection Photos



Photo 4. Vegetation is well established along the fill slope of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08897 | Date: 5/24/2021