

# Inspection Photos

API: 071-08847

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 5/24/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-08847 | Date: 5/24/2021

## Inspection Photos



**Photo 1.** Facing west toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08847 | Date: 5/24/2021

## Inspection Photos



**Photo 2.** The vegetation is well established in the interim reclamation area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08847 | Date: 5/24/2021

## Inspection Photos



**Photo 3.** Well sign posted at meter shed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08847 | Date: 5/24/2021

## Inspection Photos



**Photo 4.** Facing toward well. It appears wastr has been cleaned up since previous inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08847 | Date: 5/24/2021

## Inspection Photos



**Photo 5.** The vegetation is well established in the interim reclamation area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08847 | Date: 5/24/2021