

Inspection Photos

Location Name: CAERUS PICEANCE LLC S. PARACHUTE FEDERAL-67S95W /28NWSW

Location ID: 334071



Photo #3904 from entrance to location.



Photo #3905 from entrance to location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC S. PARACHUTE FEDERAL-67S95W /28NWSW

Location ID: 334071



Photo #3906 Location lacks stabilization.



Photo #3907 Location lacks stabilization.



Inspection Photos

Location Name: CAERUS PICEANCE LLC S. PARACHUTE FEDERAL-67S95W /28NWSW

Location ID: 334071



Photo #3908 No form of tracking BMP located at the entrance to location.



Photo #3909 No battery sign located at the tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources