

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /28NWSE

Location ID: 334065



Photo #3910 from entrance to location.



Photo #3911 from entrance to location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /28NWSE

Location ID: 334065



**Photo #3912 No battery sign located at the tank batteries.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources