

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA-67S95W /34NWNW

Location ID: 334179



Photo #3913 from entrance to location.



Photo #3916 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA-67S95W /34NWNW

Location ID: 334179



Photo #3917 from entrance to location.



Photo #3914 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA-67S95W /34NWNW

Location ID: 334179



Photo #3918 Location lacks stabilization.



Photo #3915 No form of tacking BMP located at entrance to location.