

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA-67S95W /27SESE

Location ID: 334317



Photo #3919 from entrance to location.



Photo #3920 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA-67S95W /27SESE

Location ID: 334317



Photo #3921 Location lacks stabilization.



Photo #3922 No form of tracking BMP located at entrance to location.