

## Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA-67S95W /34SENW

Location ID: 334384



Photo #3923 from entrance to location.



Photo #3924 from entrance to location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA-67S95W /34SENW

Location ID: 334384



Photo #3925 from entrance to location.



Photo #3926 Unused chemical tank.





## Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA-67S95W /34SENW

Location ID: 334384



**Photo #3927 Location lacks stabilization.**



**Photo #3928 Location lacks stabilization.**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA-67S95W /34SENW

Location ID: 334384



**Photo #3929 No form of tracking BMP located at the entrance to location.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources