

Inspection Photos

5/21/2021

Operator: SG INTERESTS I LTD - 77330

Location ID: 422990

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 422990



Photo 1: Photo taken from the cut slopes on the north end of the Location, facing east. Previous inspection documented that control measures to protect/stabilize the slopes on the Location were missing or insufficient in accordance with Rule 1002.f.(2)C. Photo shows control measures to protect/stabilize slopes on the Location remain missing or insufficient.



Inspection Photos

Operator Name: SG INTERESTS I LTD - 77330

Location ID: 422990



Photo 2: Photo taken from the cut slopes on the north end of the Location, facing west.
See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 422990



Photo 3: Photo taken from the cut slopes on the north end of the Location, facing east.
See comments under photo 1.

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 422990



Photo 4: Photo taken from the southeast corner of the Location. Photo shows slope drain. Previous inspections documented that the slope drain was not constructed with an appropriate outlet per good engineering practices. Photo shows slopes drain has not been constructed with an appropriate outlet. Photo also shows slope drain has not been properly secured.



Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 422990



Photo 5: Photo taken from the southwest corner of the Location. Photo shows slope drain. Previous inspections documented that the slope drain was not constructed with an appropriate outlet per good engineering practices. Photo shows slopes drain has not been constructed with an appropriate outlet. Photo also shows slope drain has not been properly secured.

