

Inspection Photos
Location Name: Sargent Farms 2B
Location ID: 318036



Photo 1 TB sign

Photo 2 Dead weeds and fresh weeds throughout TB location.

Inspection Photos
Location Name: Sargent Farms 2B
Location ID: 318036



Photo 3 TB weeds inside, outside & on TB berm

Photo 4 Dead weeds and fresh weeds throughout TB location around Gas Meter Run & Horiz. Heated Sep..

Inspection Photos
Location Name: Sargent Farms 2B
Location ID: 318036



Photo 7 Dead/live weeds around Horizontal Heated Separator.

Photo 8 Dead/live weeds around Horizontal Heated Separator.

Inspection Photos
Location Name: Sargent Farms 2B
Location ID: 318036



Photo 9 Wellsite in middle of planted field