


**Inspection Photos**  
**Location Name: Champlin 246 Amoco A1**  
**Location ID: 318843**



**Photo 1 WH sign**



**Photo 2 WH.**

Inspection Photos  
Location Name: Champlin 246 Amoco A1  
Location ID: 318843



Photo 3 TB sign



Photo 4 TB.

**Inspection Photos**  
**Location Name: Champlin 246 Amoco A1**  
**Location ID: 318843**



**Photo 5 Horizontal Heated Separator**



**Photo 6 Pig launchers**

# Inspection Photos

Location Name: Champlin 246 Amoco A1  
Location ID: 318843



Photo 7 Gas Meter Run




Photo 8 Card in meter house indicates calibration is current