

**Inspection Photos**  
**Location Name: Peterson 30-41**  
**Location ID: 309819**



May 24, 2021 at 8:22:34 AM  
+40.3757 -104.4718  
Weld  
Colorado Oil & Gas Conservation Commission

**Photo #1 Well**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: Peterson 30-41**  
**Location ID: 309819**



**Photo #2 Split tubing on the casing side “mechanical conditions”**



**Photo #3 Split tubing on the casing side “mechanical conditions”**

